
Monday, 22/10/2007 2:17:19 PM 4. Split Date: **Process Sheet** Linda Lacelle User : ARM **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer Job Number **Estimate Number** : D3560043 Part Number : D3560 LANDER REVIEW P.O. Number **Drawing Number** : 22/10/2007 S.O. No. : : N/A This Issue Project Number : NC Prsht Rev. **Drawing Revision** : SMALL /MED FAB Type : 11 First Issue Material : 35031 Each Previous Run : 29/10/2007 **Due Date** Written By Checked & Approved By 07.05.24 EC New Issue : Est Rev:A Comment EC 07.10.09 ECN 987 Est Rev B Additional Product Job Number: Description: Machine Or Operation: Seg. #: 6061-T6 Bar .50" x 5.0" M6061T6B0500X05000 1.0 Total: 19.0365 f(s) 1.3598 f(s)/Unit Comment: Qty.: 6061-T6 Bar 0.50" x 5.00" Batch: M106182 BAND SAW BAND SAW 2.0 Comment: BAND SAW 14 Cut blanks 15.500" long HAAS CNC VERTICAL MACHINING #1 3.0 HAAS1 Comment: HAAS CNC VERTICAL MACHINING #1 1- Mill as per Folio FA695 Rev: A Dwg D3560 Rev: 2-C'sink 0.196" hole on manual mill as per dwg D3560 3-Deburr per dwg D3560 INSPECT PARTS AS THEY COME OFF MACHINE QC2 4.0 Comment: INSPECT PARTS AS THEY COME OFF MACHINE SECOND CHECK QC8 5.0 Comment: SECOND CHECK



Date: **Process Sheet** Linda Lacelle User: Drawing Name: ARM Customer: CU-DAR001 Dart Helicopters Services Part Number: D3560043 Job Number: 35297 Job Number: Description: Machine Or Operation: Seq. #: PLATE D35921 6.0 1.0000 Each(s)/Unit Total: 14.0000 Each(s) Comment: Qty.: 08.01.31 PLATE LARGE FABRICATION RESOURCE 1 7.0 LARGE FAB 1 Comment: LARGE FABRICATION RESOURCE 1 1-Weld assembly as per dwg D3560 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (60 8- on one side weld from bottom to top half-way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near end) 11- same for remaining side (ease off pedal near end) INSPECT WORK TO CURRENT STEP QC5 8.0 WORK TO CURRENT STEP Comment: INSPEC VISUAL WELDING INSPECTION QC9 Comment: VISUAL WELDING INSPECTION HAND FINISHING RESOURCE #1 HAND FINISHING1 10.0 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 INSPECT POWDER COAT/CHEMICAL CONVERSION 11.0 08-02-04 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION



Date: Monday, 22/10/2007 2:17:19 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: ARM Job Number: 35297 Part Number: D3560043 Job Number: Seq. #: Machine Or Operation: Description: 12.0 D2808 Spacer Comment: Qty.: Total: 14.0000 Each(s) Spacer batch: 13.0 SMALL FAB SMALL & MEDIUM FAB RESOURCE 1 Comment: SMALL & MEDIUM FAB RESOURCE 1 1-Press bushing in D3560 arm per dwg D3562 14.0 QC5 INSPECT WORK TO Comment: INSPECT WORK TO CURRENT STEP 15.0 PACKAGING ' PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Identify and Stock Location: 16.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE Job Completion mi 2008/2/04



•	n-c/41		
- PARACE LTD	Work Order:	57611	
DART AEROSPACE LTD			
The second secon	Part Number:	D3560-3	
Description: Arm			
		Page 1 of 1	
Inspection Dwg: D3560 Rev: B			


FIRST ARTICLE INSPECTION CHECKLIST

X First Article	Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	5065	/			
Ø0.196	+0.005/-0.001	.196	/			
Ø1.000	+0.010/-0.001	1000	~			
Ø0.900	+0.010/-0.001	.899	/			2
0.500	+/-0.010	,502	/			
0.250	+/-0.010	.250	/	45		
0.275	+/-0.010	.276	~			
0.188	+/-0.010	.199	/			
2.000	+/-0.010	2.002	/			
1.750	+/-0.010	1.752	/			
1.702	+/-0.010	1.704	/			
Ø0.385 x 100°	+/-0.010 x 0.5°	.391				
0.250 Deep	+/-0.010	.250				
				1		
			**			

		- 1	Prototype Approval:	N/A
Measured by:	Audited by:		Date:	N/A
Date: 07/12/07	Date:	07/17/07	In lead by	Approved


			Revised by	Approved
Rev	Date	Change	KJ/JLM	
	07.01.17	New Issue	KJ/JLM	
В	07.06.13	Dimensions updated per Dwg Rev B		




D3560-1 ARM (-041, SHOWN)
OR D3560-2 ARM (-042, OPPOSITE)


D3592-1 PLATE,
SEE DETAIL A

D3560-041 ARM WELDMENT (SHOWN), D3560-042 ARM WELDMENT (OPPOSITE)



D3560-043 ARM WELDMENT (SHOWN), D3560-044 ARM WELDMENT (OPPOSITE)





DETAIL A (SCALE 1:1)

Mossum

GENERAL NOTES

- 1) WELD PER QSI 004
- 2) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1
- 3) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
- 4) ALL DIMENSIONS ARE IN INCHES

DATE

07.06.19



07.10.22 DE

SCALE

	A STATE OF THE STA						
	С		07.06.19	REMOVE POWD	ER COAT		
	В		07.01.15	REDESIGN AS	WELDMENT, ADD POCKETS		
	A		06.09.25	NEW ISSUE			
4	DESIGN	9	DRAWN BY	DART	DART AEROSPACE LTD.		
	CHECKS	#	APPROVED	DRAWING NO. D3560	REV. C SHEET 1 OF 3		

ARM WELDMENT

TITLE

COPYRIGHT @ 2008 BY DART AEROSPACE LTD.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR MY PUPPOSE OR COPIED OR COMMUNICATED TO MY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

